

# Drehmomentkurven mit Leistungsteil smd276, SM-V2xx

## Torque Curves with Power Drive smd276, SM-V2xx




**STEPPER MOTOR**  
- sm26xht-F4.2A-008  
- magnetic saturation at  
> 7Amps@10000 steps/rev




**POWER DRIVE**  
- 80V / 8A (peak)  
- 200...10000 steps/rev


Motor: sm266ht-KF4.2A-008 Drive:smd276 Umotor: 24V, 48V, 72V Inom:4.2A Imax:5,5A 1000 Steps/Rev



Motor: sm267ht-KF4.2A-008 Drive:smd276 Umotor: 24V, 48V, 72V Inom:4.2A Imax:6A 1000 Steps/Rev



Motor: sm268ht-KF4.2A-008 Drive:smd276 Umotor: 24V, 48V, 72V Inom: 4.2A Imax:7A 1000 Steps/Rev



Industrial Stepper Drive Solutions